

- (i) the  $r$  the point goes out of the control limits at the  $x$ th sample and the probability of this is  $p_n$ , and
- (ii) In the remaining  $(x - 1)$  samples, exactly  $(r - 1)$  points go out of the control limits, and its probability is :

$${}^{x-1}C_{r-1} p_n^{r-1} (1 - p_n)^{x-r}$$

Hence, by the compound probability theorem, the required probability is given by

$$P(E) = P(i). P(ii) = p_n \cdot {}^{x-1}C_{r-1} p_n^{r-1} (1 - p_n)^{x-r}$$

$$= (p_n / 1 - p_n)^r \cdot {}^{x-1}C_{r-1} (1 - p_n)^x ; x \geq r$$

### 1.9. CONTROL CHART FOR ATTRIBUTES

*Restriction (or) Limitation of  $\bar{X}$  and  $R$  chart.*

In spite of wide applications of  $\bar{X}$  and  $R$ - (or  $\sigma$ ) charts as a powerful tool of diagnosis of sources of trouble in a production process, their use is restricted because of the following imitations :

1. They are charts for variables only, i.e., for quality characteristics which can be measured and expressed in numbers.
2. In certain situations they are impracticable and un-economical, e.g., if the number of measurable characteristics, each of which could be a possible candidate for  $\bar{X}$  and  $R$  charts, is too large, say 30,000 or so then obviously there can't be 30,000 control charts.

As an alternative to  $\bar{X}$  and  $R$ -charts, we have the control chart for attributes which can be used for quality characteristics :

- (i) which can be observed only as attributes by classifying an item as defective or non-defective i.e., conforming to specifications or not, and
- (ii) which are actually observed as attributes even though they could be measured as variables, e.g., go and no-go gauge test results.

There are two control charts for attributes :

- (a) Control chart for fraction defective ( $p$ -chart) or the number of defectives ( $np$  or  $d$  chart).
- (b) Control chart for the number of defects per unit ( $c$ -chart).

**1.9.1. Control Chart for Fraction Defective ( $p$ -chart).** While dealing with attributes, a process will be adjudged in statistical control if all the samples or sub-groups are ascertained to have the same population proportion  $P$ .

If ' $d$ ' is the number of defectives in a sample of size  $n$ , then the sample proportion defective is  $p = d/n$ . Hence,  $d$  is a binomial variate with parameters  $n$  and  $P$ .

$$E(d) = nP \quad \text{and} \quad \text{Var}(d) = nPQ, \quad Q = 1 - P$$

$$\text{Thus } E(p) = E(d/n) = \frac{1}{n} E(d) = P \quad \text{and} \quad \text{Var}(p) = \text{Var}(d/n) = \frac{1}{n^2} \text{Var}(d) = \frac{PQ}{n} \quad \dots(1.7)$$

Thus, the 3- $\sigma$  control limits for  $p$ -chart are given by :

$$E(p) \pm 3 \text{ S.E. } (p) = P \pm 3 \sqrt{PQ/n} = P \pm A \sqrt{PQ}$$

where  $A = 3/\sqrt{n}$  has been tabulated for different values of  $n$ .

$$A = (3/\sqrt{n}) \dots(1.8)$$



Defect - U<sub>B</sub> of defective - U<sub>B</sub> of non-defect

✓ **Case (i) Standards specified.** If  $P'$  is the given or known value of  $P$ , then

$$UCL_p = P' + A\sqrt{P'(1-P')} \quad ; \quad LCL_p = P' - A\sqrt{P'(1-P')} \quad ; \quad CL_p = P' \quad \dots(1.8a)$$

✓ **Case (ii) Standards not specified.** Let  $d_i$  be the number of defectives and  $p_i$  the fraction defective for the  $i$ th sample ( $i = 1, 2, \dots, k$ ) of size  $n_i$ . Then the population proportion  $P$  is estimated by the statistic  $\bar{p}$  given by:

$p = \frac{d}{n}$

$$\bar{p} = \frac{\sum d_i}{\sum n_i} = \frac{\sum n_i p_i}{\sum n_i} \quad \dots(1.8b)$$

$P_i = \frac{d_i}{n_i}$

$d_i = n_i p_i$

$E(d) = nP$   
Proportion

It may be remarked here that  $\bar{p}$  is an unbiased estimate of  $P$ , since

$$E(\bar{p}) = \sum_i E(d_i) / \sum_i n_i = \left[ \sum_i (n_i P) / \sum_i n_i \right] = P$$

In this case

$$UCL_p = \bar{p} + A\sqrt{\bar{p}(1-\bar{p})} \quad ; \quad LCL_p = \bar{p} - A\sqrt{\bar{p}(1-\bar{p})} \quad ; \quad CL_p = \bar{p} \quad \dots(1.8c)$$

**1.9.2. Control Chart for Number of Defectives (d-chart).** If instead of  $p$ , the sample proportion defective, we use  $d$ , the number of defectives in the sample, then the 3- $\sigma$  control limits for  $d$ -chart are given by:

$$E(d) \pm 3 \text{ S.E. } (d) = nP \pm 3\sqrt{nP(1-P)} \quad \dots(1.9)$$

$\rightarrow$  (or) NP chart

✓ **Case (i) Standards specified.** If  $P'$  is the given value of  $P$  then

$$UCL_d = nP' + 3\sqrt{nP'(1-P')} \quad ; \quad LCL_d = nP' - 3\sqrt{nP'(1-P')} \quad ; \quad CL_d = nP' \quad \dots(1.9a)$$

✓ **Case (ii) Standards not specified.** Using  $\bar{p}$  as an estimate of  $P$  as in (1.8b), we get

$$UCL_d = n\bar{p} + 3\sqrt{n\bar{p}(1-\bar{p})} \quad ; \quad LCL_d = n\bar{p} - 3\sqrt{n\bar{p}(1-\bar{p})} \quad ; \quad CL_d = n\bar{p} \quad \dots(1.9b)$$

Since  $p$  cannot be negative, if  $LCL$  as given by above formulae comes out to be negative, then it is taken to be zero.)

✓ **Remarks 1.  $p$  and  $d$ -charts for Fixed Sample Size.** If the sample size remains constant for each sample i.e., if  $n_1 = n_2 = \dots = n_k = n$ , (say), then using (1.8b) an estimate of the population proportion  $p$  is given by:

$p = \frac{d}{n}$   
 $d = np$

$$\hat{p} = \bar{p} = \frac{\sum_{i=1}^k d_i}{\sum_{i=1}^k n_i} = \frac{\sum d_i}{nk} = \frac{n \sum_{i=1}^k p_i}{nk} = \frac{1}{k} \sum_{i=1}^k p_i \quad \dots(1.9c)$$

In this case, the same set of control limits can be used for all the samples inspected and it is immaterial if one uses  $p$ -chart or  $d$ -chart. - np-chart

**2.  $p$  and  $d$ -charts for Variable Sample Size. Method I.** If the number of items inspected ( $n$ ) in each sample varies, for  $p$ -chart separate control limits have to be computed for each sample while the central line is invariant whereas for  $d$ -chart control limits as well as the central line has to be computed for each sample. This type of limits are known as *variable control limits*. In such a situation  $p$ -chart is relatively simple and is preferred to  $d$ -chart which becomes very confusing.

**Method 2.** As pointed out in Remark 2, if  $n$  varies, separate control limits are calculated for each sample. Since  $\text{S.E. } (p) = \sqrt{PQ/n}$ , it should be noted that smaller the sample size wider the control band and *vice versa*. If the sample size does not vary appreciably then a



single set of control limits based on the average sample size  $\left(\frac{\sum_{i=1}^k n_i}{k}\right)$  can be used. For practical purposes, this holds good for situations in which the largest sample size does not exceed the smallest sample size by more than 20% of the smallest sample size.

Alternatively, for all sample sizes two sets of limits, one based on the largest sample size and the other based on the smallest sample size can be used. The largest sample size gives the smallest control band which is called *inner band* and the smallest sample size gives the largest control band which is called *outer band*. Points falling within the inner band indicate the process in control while points lying outside the outer band are indicative of the presence of assignable causes of variation which must be searched and rectified. For other points, action should be based on the exact control limits.

**Method 3.** Another procedure is to standardise the variate, i.e., instead of plotting  $p$  or  $d$  on the control chart, we plot the corresponding standardised values, viz.,

$$Z = \frac{p - p'}{\sqrt{P'Q'/n}} \text{ or } \frac{p - \bar{p}}{\sqrt{\bar{p}(1-\bar{p})/n}} \quad \dots(1.10)$$

According as  $P$  is given or not, the symbols having their usual meanings. This stabilises our variable and the resulting chart is called *stabilised p-chart* or *d-chart*. In this case the control limits as well as the central line for  $p$  and  $d$ -charts are invariant with  $n$  (i.e., they are constants independent of  $n$ ) being given by :

$$UCL = 3, \quad CL = 0, \quad LCL = -3 \quad \dots(1.10a)$$

Hence, the problem of variable control limits can be solved with a little more computational work discussed above.

**Interpretations of p-chart.** 1. From the  $p$ -chart a process is judged to be in statistical control in the same way as is done for  $\bar{X}$  and  $R$  charts. If all the sample points fall within the control limits without exhibiting any specific pattern, the process is said to be in control. In such a case, the observed variations in the fraction defective are attributed to the stable pattern of chance causes and the average fraction defective  $\bar{p}$  is taken as the standard fraction defective  $P$ .

2. Points outside the  $UCL$  are termed as *high spots*. These suggest deterioration in the quality and should be regularly reported to the production engineers. The reasons for such deterioration could possibly be known and removed if the details of conditions under which data were collected, were known. Of particular interest and importance is, if there was any change of inspection or inspection standards.

3. Points below  $LCL$  are called *low spots*. Such points represent a situation showing improvement in the product quality. However, before taking this improvement for guaranteed, it should be investigated if there was any slackness in inspection or not.

4. (When a number of points fall outside the control limits, a revised estimate of  $P$  should be obtained by eliminating all the points that fall above  $UCL$  (it is assumed that points that fall below  $LCL$  are not due to faulty inspection). The standard fraction defective  $P$  should be revised periodically in this way.)

**Remark.** The interpretation for the control chart for number of defects ( $d$ -chart) is same as that for  $p$ -chart.



*p-chart for fixed sample size*

**Example 1-10.** The following are the figures of defectives in 22 lots each containing 2,000 rubber belts :

425, 430, 216, 341, 225, 322, 280, 306, 337, 305, 356,  
402, 216, 264, 126, 409, 193, 326, 280, 389, 451, 420

Draw control chart for fraction defective and comment on the state of control of the process.

**Solution.** Here we have a fixed sample size  $n = 2,000$  for each lot. If  $d_i$  and  $p_i$  are respectively the number of defectives and the sample fraction defective for the  $i$ th lot, then

*$p = \frac{d_i}{n}$  - fixed sample*

$$p_i = \frac{d_i}{2,000}, (i = 1, 2, \dots, 22)$$

which are given in Table 1-2.

*d = defective, Sample fraction defective*

TABLE 1-2 : COMPUTATIONS FOR C.C. FOR FRACTION DEFECTIVE

S. No.	d	$p = (d/2000)$	S. No.	d	$p = (d/2000)$
1	425	0.2125	12	402	0.2010
2	430	0.2150	13	216	0.1080
3	216	0.1080	14	264	0.1320
4	341	0.1705	15	126	0.0630
5	225	0.1125	16	409	0.2045
6	322	0.1610	17	193	0.0965
7	280	0.1400	18	326	0.1630
8	306	0.1530	19	280	0.1400
9	337	0.1685	20	389	0.1945
10	305	0.1525	21	451	0.2255
11	356	0.1780	22	420	0.2100
Total	3,543	1.7715		3,476	1.7380

In the usual notations, we have

*k = 22 lots, each containing n = 2000 rubber belts*

$$\bar{p} = \frac{\sum p_i}{k} = \frac{1.7715 + 1.7380}{22} = \frac{3.5095}{22} = 0.1595 \Rightarrow \bar{q} = 1 - \bar{p} = 0.8405$$

[Or  $\bar{p} = \frac{\sum d_i}{nk} = \frac{3543 + 3476}{2000 \times 22} = \frac{7019}{44000} = 0.1595$ ]

*$\bar{p} = \frac{\text{Total no. of defectives}}{\text{Total no. of units inspected}}$*

3- $\sigma$  control limits for p-chart are given by :

$$\bar{p} \pm 3 \sqrt{\bar{p} \bar{q} / n} = 0.1595 \pm 3 \sqrt{0.1595 \times 0.8405 / 2000}$$

$$= 0.1595 \pm 3 \sqrt{0.000067} = 0.1595 \pm 0.0246$$

*$\bar{p} \pm 3\hat{\sigma}_p$*

$UCL_p = 0.1595 + 0.0246 = 0.1841; LCL_p = 0.1595 - 0.0246 = 0.1349; CL_p = \bar{p} = 0.1595$

*where  $\hat{\sigma}_p = \sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$*

*$\bar{p} \pm 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$  and  $\bar{p} \pm 3\hat{\sigma}_p$*



1.34

The control chart for fraction defective ( $p$ -chart) is drawn in Fig. 1-9.

From the  $p$ -chart, we find that the sample points (fraction defectives) corresponding to the sample numbers 1, 2, 3, 5, 12, 13, 14, 15, 16, 17, 20, 21 and 22, fall outside the control limits. Hence, the process cannot be regarded in statistical control.

CONTROL CHART FOR FRACTION DEFECTIVE




Fig. 1-9

**Example 1-11.** From the following inspection results, construct  $3\text{-}\sigma$  control limits for  $p$  chart :

Date Sept.	No. of Defectives	Date Sept.	No. of Defectives	Date Sept.	No. of Defectives
1	22	11	70	21	66
2	40	12	80	22	50
3	36	13	44	23	46
4	32	14	22	24	32
5	42	15	32	25	42
6	40	16	42	26	46
7	30	17	20	27	30
8	44	18	46	28	38
9	42	19	28	29	40
10	38	20	36	30	24

The sub-groups, from which the defectives were taken out, were of the same size, i.e., 1,000 items each.

Without constructing the control chart, comment on the state of control of the process the process is out of control, then suggest the revised control limits for future use.

**Solution.** Here we have a fixed sample size for each lot. If  $d_i$  and  $p_i$  are respectively the number of defectives and the sample fraction defective for the  $i$ th lot then

$$p_i = \frac{d_i}{1,000}, \quad (i = 1, 2, \dots, 30)$$

which are given in Table 1-3 :

*p-chart for fixed Sample Size*

*2e*

*Wt*



TABLE 1.3 : CALCULATIONS FOR CONTROL LIMITS FOR p-CHART

Date Sept.	No. of defectives	Fraction defectives	Date Sept.	No. of defectives	Fraction defective	Date Sept.	No. of defectives	Fraction defectives
1	22	0.022	11	70 ✓	0.070 ✓	21	66 ✓	0.066 ✓
2	40	0.040	12	80 ✓	0.080 ✓	22	50	0.050
3	36	0.036	13	44	0.044	23	46	0.046
4	32	0.032	14	22	0.022	24	32	0.032
5	42	0.042	15	32	0.032	25	42	0.042
6	40	0.040	16	42	0.042	26	46	0.046
7	30	0.030	17	20 ✓	0.020 ✓	27	30	0.030
8	44	0.044	18	46	0.046	28	38	0.038
9	42	0.042	19	28	0.028	29	40	0.040
10	38	0.038	20	36	0.036	30	24	0.024
Total	366	0.366	Total	420	0.420	Total	414	0.414

From the above table, we have

$$\sum d_i = 366 + 420 + 414 = 1,200 ; \quad \sum p_i = 0.366 + 0.420 + 0.414 = 1.200 ; \quad n = 1000, \quad k = 30$$

$$\bar{p} = \frac{\sum d}{nk} = \frac{1200}{1000 \times 30} = 0.040 \quad \text{or} \quad \bar{p} = \frac{\sum p_i}{k} = \frac{1.2}{30} = 0.040$$

3-σ Control Limits for p-Chart :  $CL_p = \bar{p} = 0.040$

$$UCL_p = \bar{p} + 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n}} = 0.040 + 3 \sqrt{\frac{0.04(1-0.04)}{1000}}$$

$$= 0.040 + 3\sqrt{0.0000384} = 0.040 + 3 \times 0.0062 = 0.0586$$

$$LCL_p = \bar{p} - 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n}} = 0.040 - 0.0186 = 0.0214.$$

We observe that the sample points (fraction defectives) on 11th, 12th, 17th and 21st September were 0.070, 0.080, 0.020 and 0.066 respectively and these fall outside the control limits. Hence the process is not in a state of statistical control.

**Revised Control Limits :** The revised control limits are obtained on eliminating these four samples and considering the remaining 30 - 4 = 26 samples.

Based on the remaining 26 samples, we get

$$CL_p = \bar{p}' = \frac{\sum d - 70 - 80 - 20 - 66}{1000 \times 26} = \frac{1200 - 236}{1000 \times 26} = \frac{964}{26000} = 0.0371$$

or  $CL_p = \bar{p}' = \frac{\sum p - 0.07 - 0.08 - 0.02 - 0.066}{26}$

$$= \frac{1.200 - 0.236}{26} = \frac{0.964}{26} = 0.0371$$

$$UCL_p = \bar{p}' + 3 \sqrt{\frac{\bar{p}' \bar{q}'}{n}} = 0.0371 + 3 \sqrt{\frac{0.0371 \times 0.9629}{1000}}$$

$$= 0.0371 + 3 \times \sqrt{0.0000357} = 0.0371 + 3 \times 0.0060$$

$$= 0.0371 + 0.0180 = 0.0551$$



$$LCL_p = \bar{p}' - 3 \sqrt{\frac{\bar{p}' \bar{q}'}{n}} = 0.0371 - 0.0180 = 0.0191$$

Since none of the remaining 26 sample points (fraction defectives) lies outside the revised control limits, [ $LCL_p = 0.0191$  and  $UCL_p = 0.0551$ ], these may be regarded as the control limits for  $p$ -chart for the future production from this process.

**Example 1-12.** 20 samples each of size 10 were inspected. The number of defectives detected in each of them is given below :

Samples No.	:	1	2	3	4	5	6	7	8	9	10
No. of defectives	:	0	1	0	3	9	2	0	7	0	1
Sample No.	:	11	12	13	14	15	16	17	18	19	20
No. of defectives	:	1	0	0	3	1	0	0	2	1	0

Construct the 'number of defectives' chart and establish quality standard for the future.

**Solution.** Here we have samples of fixed size  $n = 10$ . The total number of defectives in all the 20 samples is :

$$\sum d = 0 + 1 + 0 + 3 + 9 + \dots + 2 + 1 + 0 = 31$$

An estimate of the process fraction defective is given by :

$$\bar{p} = \frac{\sum d}{nk} = \frac{31}{10 \times 20} = 0.155 \Rightarrow \bar{q} = 1 - \bar{p} = 0.845$$

The 3- $\sigma$  control limits for 'number defectives' chart ( $np$ -chart) are given by :


$$CL_{np} = n\bar{p} = 1.55$$

$$UCL_{np} = n\bar{p} + 3\sqrt{n\bar{p}(1-\bar{p})} = 1.55 + 3\sqrt{1.55 \times 0.845} = 1.55 + 3.43 = 4.98$$

$$LCL_{np} = n\bar{p} - 3\sqrt{n\bar{p}(1-\bar{p})} = 1.55 - 3\sqrt{1.55 \times 0.845} \approx 0 \text{ (Negative)}$$

The control chart for the 'number of defectives' is obtained on plotting the number of defectives against the corresponding sample number and is given in Fig. 1-10.

**np-Chart**



**Fig. 1-10. np-chart.**

*np-chart for fixed sample size*

*No. of defectives given*

*n=10  
k=20*



Since two points corresponding to 5th and 8th samples lie outside the control limits, we conclude that the process is not in a state of statistical control. To establish quality standards for the future, we eliminate these points.

Deleting sample numbers 5 and 8, we compute  $CL$ ,  $UCL$  and  $LCL$  based on the remaining  $20 - 2 = 18$  samples as follows :

**Revised Control Limits for Future :**

$$\bar{p}' = \frac{\sum d - 9 - 7}{10 \times 18} = \frac{31 - 16}{180} = \frac{15}{180} = 0.083 \quad \Rightarrow \quad \bar{q}' = 1 - \bar{p}' = 0.917$$

$$CL' = n\bar{p}' = 10 \times 0.083 = 0.83$$

$$UCL' = n\bar{p}' + 3\sqrt{n\bar{p}'(1-\bar{p}')} = 0.83 + 3\sqrt{0.83 \times 0.917} = 0.83 + 2.62 = 3.45$$

$$LCL' = n\bar{p}' - 3\sqrt{n\bar{p}'(1-\bar{p}')} = 0.83 - 3\sqrt{0.83 \times 0.917} = -0.178 = 0.$$

These revised values are shown in the (on page 1.36) as the revised  $UCL'$  and  $LCL'$  respectively. No sample values other than those which have been deleted, fall outside the new limits. We take these new limits, alongwith the new central line, as standards for controlling product in the future.

**Example 1.13.** The following data give the number of defectives in 10 independent samples of varying sizes from a production process :

Sample No.	:	1	2	3	4	5	6	7	8	9	10
Sample size	:	2,000	1,500	1,400	1,350	1,250	1,760	1,875	1,955	3,125	1,575
No. of defectives	:	425	430	216	341	225	322	280	306	337	305

Draw the control chart for fraction defective and comment on it.

**Solution.** Since we have variable sample size, we can draw the control chart for fraction defective in the following three ways.

**Method 1. Variable Control Limits.** In this case we calculate  $3-\sigma$  limits for each sample separately by using the formula :

$$UCL = \bar{p} + 3\sqrt{\bar{p}\bar{q}/n_i} \quad \text{and} \quad LCL = \bar{p} - 3\sqrt{\bar{p}\bar{q}/n_i}, \quad \text{where} \quad \bar{p} = \frac{\sum d_i}{\sum n_i} = \frac{3,187}{17,790} = 0.1791...(*)$$

and  $d_i =$  No. of defectives in the  $i$ th sample,  $n_i =$  sample size of the  $i$ th sample

$$\therefore \bar{q} = 1 - \bar{p} = 0.8209. \quad \text{Thus, } \bar{p}\bar{q} = 0.1791 \times 0.8209 = 0.1470231$$

For computation of the variable control limits, see the calculation in Table 1.4.

TABLE 1.4 : COMPUTATIONS FOR  $p$ -CHART (VARIABLE CONTROL LIMITS)

$n$	$d$	$p = d/n$	$\bar{p}\bar{q}/n$	$\sqrt{\bar{p}\bar{q}/n}$	$3 \times \sqrt{\bar{p}\bar{q}/n}$	$\bar{p} + 3\sqrt{\bar{p}\bar{q}/n}$ UCL	$\bar{p} - 3\sqrt{\bar{p}\bar{q}/n}$ LCL
2,000	425	.2125	.0000735	.008573	.025719	0.205	0.153
1,500	430	.2867	.000098	.009899	.029698	0.209	0.149
1,400	216	.1543	.000105	.010247	.030741	0.210	0.148
1,350	341	.2526	.000109	.010440	.031321	0.210	0.148
1,250	225	.1800	.000118	.010863	.032588	0.212	0.147

$$\bar{p}\bar{q} = \frac{0.1470231}{2000}$$

$$0.1791 + 0.025719 = 0.2048$$

$$0.1791 - 0.025719 = 0.153381$$



1-38

1,760	322	.1829	.000084	.009138	.027413	.207	.152
1,875	280	.1495	.000078	.008854	.026562	.206	.153
1,955	306	.1565	.000075	.008672	.026015	.205	.153
3,125	337	.1078	.000047	.006856	.020567	.200	.159
1,575	305	.1937	.000093	.009659	.028977	.208	.150
17,790	3,187	1.8763					

From the chart [Fig. 1-11], it is obvious that a number of sample points corresponding to sample numbers 1, 2, 4, 7 and 9 are outside the respective control limits. Hence the process is not in a state of statistical control. This suggests the presence of some assignable causes of variations, which should be detected and eliminated.




Fig. 1-11

**Method 2.** Here we set up two sets of control limits, one based on the maximum sample size  $n = 3,125$  (corresponding to 9th sample) and the other based on the minimum sample size  $n = 1,250$  (corresponding to 5th sample). From the table, we note that the corresponding sets of control limits are:

For  $n = 3,125$ ;  $UCL = 0.1997$  and  $LCL = 0.1585$ ; For  $n = 1,250$ ;  $UCL = 0.2117$  and  $LCL = 0.1465$ .

From the control chart [Fig. 1-12], we find that the sample points corresponding to sample number 1, 2, 4 and 9 lie outside




Fig. 1-12



the outer band (based on minimum sample size), and hence the process is out of statistical control.

**Method 3.** We standardise the statistic  $p$  by the formula :

$$Z_i = \frac{p_i - E(p_i)}{S.E. (p_i)} = \frac{p_i - \bar{p}}{\sqrt{\bar{p}q/n}}, \dots (*)$$

where  $\bar{p}$  is computed in (\*) and plot the Z-values against the corresponding sample number. Since  $n$  is large,  $Z_i \sim N(0, 1)$  and hence

$$UCL_z = 3 ; LCL_z = -3 ; CL_z = 0$$

TABLE 1-5 : COMPUTATIONS OF Z-VALUES

$p$	$p - \bar{p}$	$\sqrt{\bar{p}q/n}$	$Z = \frac{p - \bar{p}}{\sqrt{\bar{p}q/n}}$
·2126	·0334	·0086	3·8841
·2867	·1076	·0099	10·8686
·1543	-·0248	·0102	-2·4313
·2526	·0735	·0104	5·25
·1800	·0009	·0109	0·0826
·1829	·0038	·0091	0·4176
·1495	-·0296	·0089	-3·2558
·1565	-·0226	·0087	-2·5977
·1078	-·0713	·0069	-10·3333
·1937	·0146	·0097	1·5052

The control chart is drawn in Fig. 1-13.

Since a number of sample values ( $Z$ ) except for sample numbers 3, 5, 6, 8 and 10 lie-outside the limits  $\pm 3$ , therefore the process is out of statistical control.




Fig. 1-13

**1-9-3. Control Chart for Number of Defects per Unit (c - Chart).** The field of application of c-chart is much more restricted as compared to  $\bar{X}$  and  $R$  charts or  $p$ -chart. Before we embark upon to discuss the theory behind c-chart, it is imperative to distinguish between defect and defective. (An article which does not conform to one or more of the specifications, is termed as defective while any instance of article's lack of conformity to specifications is a defect.) Thus, every defective contains one or more of the defects, e.g., a defective casting may further be examined for blow holes, cold shuts, rough surface, weak structure, etc.

Unlike  $d$  or  $np$ -chart which applies to the number of defectives in a sample, c-chart applies to the number of defects per unit. Sample size for c-chart may be a single unit like a radio, or group of units or it may be a unit of fixed time, length, area, etc. For example, in

*Handwritten notes in Tamil script at the bottom of the page, including the word 'பொருள்' (meaning).*



case of surface defects, area of the surface is the sample size ; in case of casting defects, a single part (such as base plate, side cover) is the sample size. However, defined sample size should be constant in the sense that different samples have essentially equal opportunity for the occurrence of defects.

✓ **Control Limits for c-chart.** In many manufacturing or inspection situations, the sample size  $n$  i.e., the area of opportunity is very large (since the opportunities for defects to occur are numerous) and the probability  $p$  of the occurrence of a defect in any one spot is very small such that  $np$  is finite. In such situations from statistical theory we know that the pattern of variations in data can be represented by Poisson distribution, and consequently 3- $\sigma$  control limits based on Poisson distribution are used. Since for a Poisson distribution, mean and variance are equal, if we assume that  $c$  is Poisson variate with parameter,  $\lambda$ , we get

$$E(c) = \lambda \text{ and } \text{Var}(c) = \lambda$$

Thus 3- $\sigma$  control limits for c-chart are given by :

$$\left. \begin{aligned} UCL_c &= E(c) + 3\sqrt{\text{Var}(c)} = \lambda + 3\sqrt{\lambda} \\ LCL_c &= E(c) - 3\sqrt{\text{Var}(c)} = \lambda - 3\sqrt{\lambda} \\ CL_c &= \lambda \end{aligned} \right\} \dots(1.11)$$

✓ **Case (i) Standards specified.** If  $\lambda'$  is the specified value of  $\lambda$ , then

$$UCL_c = \lambda' + 3\sqrt{\lambda'} ; LCL_c = \lambda' - 3\sqrt{\lambda'} ; CL_c = \lambda' \dots(1.12)$$

✓ **Case (ii) Standards not Specified.** If the value of  $\lambda$  is not known, it is estimated by the mean number of defects per unit. Thus, if  $c_i$  is the number of defects observed on the  $i$ th ( $i = 1, 2, \dots, k$ ) inspected unit, then an estimate of  $\lambda$  is given by :

$$\hat{\lambda} = \bar{c} = \sum_{i=1}^k c_i / k \dots(1.12a)$$

$E(c) = \lambda$

It can be easily seen that  $\bar{c}$  is an unbiased estimate of  $\lambda$ . The control limits, in this case, are given by :  $UCL_c = \bar{c} + 3\sqrt{\bar{c}} ; LCL_c = \bar{c} - 3\sqrt{\bar{c}} ; CL_c = \bar{c} \dots(1.12b)$

Since  $c$  can't be negative, if  $LCL$  given by above formulae comes out to be negative, it is regarded as zero.

The central line is drawn at  $\bar{c}$ , and  $UCL$  and  $LCL$  are drawn at the values given by (1.12a). The observed number of defects on the inspected units are then plotted on the control chart. The interpretations for c-chart are similar to those of p-chart.)

**Remark.** Usually  $k$ , the number of samples (inspected units), is taken from 20 to 25. Normal approximation to Poisson distribution may be used provided  $\bar{c} < 5$ .

Varying Sample Size

✓ **1.9.4. c-Chart for Variable Sample Size or u-Chart.** In this case instead of plotting  $c$ , the statistic  $u = c/n$  is plotted,  $n$  being the sample size which is varying. If  $n_i$  is the sample size and  $c_i$  the total number of defects observed in the  $i$ th sample, then

$$u_i = c_i / n_i, (i = 1, 2, \dots, k), \dots(1.13)$$

gives the average number of defects per unit for the  $i$ th sample.

In this case an estimate of  $\lambda$ , the mean number of defects per unit in the lot, based on all the  $k$ -samples is given by :

$$\hat{\lambda} = \bar{u} = \frac{1}{k} \sum_{i=1}^k u_i \dots(1.13a)$$

Varying Sample Size  
 $i=1, 2, \dots, k$



*c-chart defects - failure, accidents, misprints, => poisson dis /*

*eg total P-224 Mahajan, book*

We know that if  $\bar{X}$  is the mean of a random sample of size  $n$  then S.E. ( $\bar{X}$ ) =  $\sigma/\sqrt{n}$ . Hence, the standard error of the average number of defects per unit is given by :

$$S.E. (u) = \sqrt{\lambda/n} = \sqrt{\bar{u}/n} \quad ; \quad [\text{On using (1.13a)}] \quad \dots(1.13b)$$

Hence, 3- $\sigma$  control limits for  $u$ -chart (or  $c$ -Chart for variable sample size) are given by :

$$UCL_u = \bar{u} + 3 \sqrt{\bar{u}/n} \quad ; \quad LCL_u = \bar{u} - 3 \sqrt{\bar{u}/n} \quad ; \quad CL_u = \bar{u} \quad \dots(1.13c)$$

As is obvious, control limits will vary for each sample. The central line, however, will be same. The interpretation of these charts is similar to the  $p$ -chart or  $d$ -chart.

### Applications of $c$ -chart

The universal nature of Poisson distribution as the law of small numbers makes the  $c$ -chart technique quite useful. In spite of the limited field of application of  $c$ -chart (as compared to  $\bar{X}$ ,  $R$ ,  $p$ -charts), there do exist situations in industry where  $c$ -chart is definitely needed. Some of the representative types of defects to which  $c$ -chart can be applied with advantage are :

1.  $c$  is number of imperfections observed in a bale of cloth.
2.  $c$  is the number of surface defects observed in (i) roll of coated paper or a sheet of photographic film, and (ii) a galvanised sheet or a painted, plated or enamelled surface of given area.
3.  $c$  is the number of defects of all types observed in aircraft sub-assemblies or final assembly.
4.  $c$  is the number of breakdowns at weak spots in insulation in a given length of insulated wire subject to a specified test voltage.
5.  $c$  is the number of defects observed in stains or blemishes on a surface.
6.  $c$  is the number of soiled packages in a given consignment.
7.  $c$ -chart has been applied to sampling acceptance procedures based on number of defects per unit, e.g., in case of inspection of fairly complex assembled units such as T.V. sets, aircraft engines, tanks, machine-guns, etc., in which there are very many opportunities for the occurrence of defects of various types and the total number of defects of all types found by inspection is recorded for each unit.

8.  $c$ -chart technique can be used with advantage in various fields other than industrial quality control, e.g., it has been applied (i) to accident statistics (both of industrial accidents and highway accidents), (ii) in chemical laboratories, and (iii) in epidemiology.

**Example 1-14.** In welding of seams, defects included pinholes, cracks, cold taps, etc. A record was made of the number of defects found in one seam each hour and is given below.

1-12-2005	8 A.M.	2	2-12-2005	8 A.M.	5	3-12-2005	8 A.M.	6
	9 A.M.	4		9 A.M.	3		9 A.M.	4
	10 A.M.	7		10 A.M.	7		10 A.M.	3
	11 A.M.	3		11 A.M.	11		11 A.M.	9
	12 A.M.	1		12 A.M.	6		12 A.M.	7
	1 P.M.	4		1 P.M.	4		1 P.M.	4
	2 P.M.	8		2 P.M.	9		2 P.M.	7
	3 P.M.	9		3 P.M.	9		3 P.M.	12

Draw the control chart for number of defects and give your comments.



**Solution.** Average number of defects per sample is :  $\bar{c} = \frac{1}{k} \sum c = \frac{1}{24} \times 144 = 6$

The control limits and the central line, therefore are as follows :

$$UCL_c = \bar{c} + 3\sqrt{\bar{c}} = 6 + 3\sqrt{6} = 13.35$$

$$LCL_c = \bar{c} - 3\sqrt{\bar{c}} = 6 - 3\sqrt{6} = -1.35$$

$$CL_c = \bar{c} = 6$$

Because the number of defects cannot be negative, so we consider the lower limit to be zero, i.e.,  $\bar{c}$  is allowed to vary between 0 and 13.35.

The control chart is drawn in Fig. 1-14.

Since none of the 24 points falls outside the control limits, process average may be regarded in state of statistical control.




Fig. 1-14

**Example 1-15.** The number of defects on 20 items are given below :

Item No.	:	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
No. of defects	:	2	0	4	1	0	8	0	1	2	0	6	0	2	1	0	3	2	1	0	2

Devise a suitable control scheme for the future.

**Solution.** The control chart to be used is the c-chart.

$$\bar{c} = \text{Average number of defects/item} = \frac{1}{k} \sum c = \frac{1}{20} \times 35 = 1.75$$

$$CL_c = \bar{c} = 1.75; UCL_c = \bar{c} + 3\sqrt{\bar{c}} = 1.75 + 3\sqrt{1.75} = 5.71; LCL_c = \bar{c} - 3\sqrt{\bar{c}} = 1.75 - 3.96 = 0.$$

Since two sample points corresponding to 6th and 11th samples lie outside the control limits, we conclude that the process is not in a state of statistical control. To establish quality standards for the future, we eliminate these 'out of control' sample points. Deleting sample numbers 6 and 11, we compute the new control limits  $CL'$ ,  $UCL'$  and  $LCL'$  for the remaining 18 samples as follows :

$$\bar{c}' = \frac{\sum c - 8 - 6}{20 - 2} = \frac{35 - 14}{18} = \frac{21}{18} = 1.17$$

$$CL' = \bar{c}' = 1.17; UCL' = \bar{c}' + 3\sqrt{\bar{c}'} = 1.17 + 3\sqrt{1.17} = 4.15;$$

$$LCL' = \bar{c}' - 3\sqrt{\bar{c}'} = 1.17 - 3\sqrt{1.17} = 0$$

It may be noted that now no sample points (c-values) other than those which have been deleted, fall outside the new control limits. We take these new limits, along with the new central line, as standards for controlling production in the future.

### 1-10. NATURAL TOLERANCE LIMITS AND SPECIFICATION LIMITS

A process in statistical control implies that the control charts for both the mean and range show complete homogeneity and in such a case, a measure of the variation of the individual products is given by the standard deviation ( $\sigma$ ), estimate by  $\bar{R}/d_2$  or  $\bar{s}/C_2$  from



control data. If  $\mu$  and  $\sigma$  are the process average and process standard deviation respectively, then the limits  $\mu \pm 3\sigma$  are called the *Natural Tolerance Limits*. The probability of an observation lying outside these limits is 0.0027. The width '6 $\sigma$ ' which is the inherent variability of the process is given a special name *Natural Tolerance*. If  $\mu$  and  $\sigma$  are not known then  $\hat{\mu} \pm 3\hat{\sigma}$  are the estimates of the natural tolerance limits where

$$\hat{\mu} = \bar{X} \quad \text{and} \quad \hat{\sigma} = \bar{R}/d_2 \quad \text{or} \quad \hat{\sigma} = \bar{s}/C_2.$$

It might happen that even though the process is in statistical control as exhibited by control charts, the customer may not be satisfied with the product. This happens when the process does not conform to *specification limits* (limits as desired or fixed by the customer) for that item. These specification limits are generally given in terms of upper and lower tolerance limits. A decision, whether a process needs adjustment or not, can be made at the point by comparing natural tolerance limits and specification limits.

**Comparison.** Let  $X_{max}$  and  $X_{min}$  denote the upper specification limit (U.S.L.) and lower specification limit (L.S.L.) respectively for some quality characteristic. When both these limits are specified, a comparison of these with the 'natural tolerance limits' may result in one of the following three situations :

- (a) *Natural tolerance is considerably smaller than specified tolerance, i.e.,  $X_{max} - X_{min} > 6\sigma$ .*

**Interpretations.** (i) In such a case almost all the manufactured items will conform to specifications as long as the process is in statistical control and is appropriately centered as in positions A, B or C as shown in the Fig. 1-15.

NATURAL TOLERANCE SMALLER THAN SPECIFIED TOLERANCE




Fig. 1-15

If the process is operating under one of these conditions,  $\bar{X}$  may be permitted to go out of control, provided it does not go too far ; in other words, the distribution of  $\bar{X}$  may be allowed to fluctuate between positions B and C. This will save the time and money for frequent machine setting and delays due to looking for assignable causes of variation which will not be responsible for unsatisfactory product.

(ii) In such a situation since, even considerable shifts in the level of working may not result in the items falling outside specification limits, the time interval between taking successive samples for control chart inspection can be appreciably increased.

(iii) The larger the ratio  $(X_{max} - X_{min})$  to the natural tolerance  $6\sigma$ , the greater is the likelihood of getting good product without assistance from any control chart. This will imply that the process is too good for the product and it may be economical to examine if relaxations in the conditions of production, e.g., less costly experiment or processing or material, could be allowed. It may also be worthwhile to 'squeeze' the specification limits, to produce a product superior to the one originally intended.

Customer  $\rightarrow$  specification limits  
 - Natural tolerance



✓ (b) Specification limits coincide with tolerance limits, i.e.,

$$X_{max} - X_{min} = 6\sigma$$

This is an ideal situation and in this case a process in statistical control obviously implies that the product is meeting the specifications. Here, careful centering of the process is all the more important and if no item is to be rejected then the process has to be centred exactly at the specification mean. Any departure from this centering would result in some of the product going outside the specification limits. As soon as a control chart detects such departure, immediate remedial action should be taken to maintain the centering of the process.

✓ (c) Natural tolerance is greater than specified tolerance, i.e.,

$$X_{max} - X_{min} < 6\sigma$$

✓ **Interpretations.** (i) If the natural tolerances are not included within the specification limits then even with the process in control and the process average perfectly centered at the specification mean, the production of an appreciable quantity of defective articles (i.e., articles not conforming to specifications) is inevitable. Here a slight shift in the process average will increase the per cent defective. In such a situation, a re-adjustment of the process is advisable with respect to either the process average or process dispersion or both.

(ii) Also it would be worthwhile to investigate the possibility of relaxing the specified tolerances to the extent of natural tolerances.

(If 100% inspection is possible, then defective articles may be sorted out and eliminated but if 100% inspection is not possible (e.g., if testing is destructive) then there is no chance of getting the product all of which will conform to specifications and the only alternative in this case is to relax the specification limits to tolerance limits.)

✓ **Modified Control Limits.** If the specification limits lie outside the natural tolerances, i.e.,  $X_{max} - X_{min} > 6\sigma$ , then modified control limits which exhibit the relationship between the specification limits and the  $\bar{x}$  values in  $\bar{X}$ -chart, may be used to permit shifts in process levels within permissible limits.

As already pointed out, in such a situation shifts in the values of  $\bar{X}$  may be allowed provided it does not go too far. This poses the question: "What are the limits within which  $\bar{X}$ -values may be allowed to vary such that the product meets the specifications?", since if the process is centered at A and B as shown in the Fig. 1-16a some of the items will naturally lie outside the specification limits.




Fig. 16a

N.T. > S.T.  
6σ > X\_max - X\_min



Let us have a look at the following figure (Fig. 1-16b) which shows the statistically controlled universe in its highest and lowest accepting positions.




Fig. 1-16b

The natural tolerances (*i.e.*, process dispersion) is  $6\sigma$ . If the universe is at the highest accepting position, then the process average (central line) will be at a distance  $3\sigma$  below USL and similarly when the universe is at its lowest accepting position, the process average is at a distance  $3\sigma$  above the LSL. Thus in this case, instead of fixed central line at  $\bar{X}$ , we have a central band so that as long as  $\bar{X}$  lies in this central band, the product will conform to specifications. The upper and lower edges of the central band are given respectively by

$$USL - 3\sigma, LSL + 3\sigma$$

For a sub-group of size  $n$ , as is clear from the figure, (the highest and lowest satisfactory values of UCL and LCL, known as Upper Rejection Limit (URL) and Lower Rejection Limit (LRL) respectively are given by :

$$URL_{\bar{X}} = USL - 3\sigma' + 3\sigma'/\sqrt{n}$$

$$LRL_{\bar{X}} = LSL + 3\sigma' - 3\sigma'/\sqrt{n}$$

These rejection limits, when used in place of control limits, are called 'modified control limits'.

### 1-11. ACCEPTANCE SAMPLING INSPECTION PLANS

In many a manufacturing process, the producer, in order to ensure that the manufactured goods are according to specifications of the customer, gets his lot checked at strategic stages. On the other hand, the customer is anxious to satisfy himself about the quality of goods he accepts. An ideal way of doing this seems to inspect each and every item presented for acceptance, *i.e.*, to resort to 100 per cent inspection. 100% inspection should be taken recourse to under the following conditions :

- (i) The occurrence of a defect may cause loss of life or serious casualty to personnel.
- (ii) A defect may cause serious malfunction of equipment.

We may also wish to examine all the items of the product under the following conditions :

- (i)  $N$ , the lot size is small, and
- (ii) The incoming quality is poor or unknown.



If testing is destructive, as for instance in the case of crackers, shells, bulbs etc, it is absolutely non-sensical to talk of 100% inspection. Even in those cases where 100% inspection is possible, it may not be desirable because (i) it is costly, and (ii) due to fatigue, impossibility of proper check, and variations in efficiencies of inspection in time, persons, and places, however careful one may be, the inspected lot is likely to contain a small percentage of defectives.

So, from practical and economic considerations sampling procedures are adopted, i.e., a lot is accepted or rejected, on the basis of the samples drawn at random from the lot. It has been found that if a scientifically designed sampling inspection plan is used, it provides adequate protection to producer as well as consumer very economically.

The main objective of inspection is to control the quality of the product by critical examination at strategic points. Sampling inspection, besides keeping down the cost of production, also ensures that the quality of a lot accepted is according to the specifications of the consumer. The guidelines of a sampling procedure are :

- (a) It should give a definite assurance against passing any unsatisfactory lot, and
- (b) The inspection expenses should be as low as possible subject to the degree of protection afforded by (a) above.

*Acceptance sampling plans refer to the use of sampling inspection by a purchaser to decide whether to accept or to reject a lot of given product. In statistical quality control terminology, it is also known as **product control**. In case of acceptance sampling by attributes, the decision for accepting or rejecting a given lot is taken on the basis whether the sample items possess a particular attribute or not. In other words, acceptance sampling by attributes is an 'attribute based inspection' that merely grades the product as defective or non-defective. If the product is found defective, it is rejected and if it is found non-defective, it is accepted.*

The necessity of acceptance sampling arises from the fact that when lot of product is transferred from one firm to another, or from one division of a firm to its another division or say, from seller to the buyer, the recipient of the lot wants to be reasonably sure that the lot meets the standards already agreed upon with regard to the quality of the product. In other words, acceptance sampling prescribes a procedure, that if applied to a series of lots, yields quality assurance by involving a decision to accept or reject a lot on the basis of random samples drawn from it.

**Acceptable Quality Level (AQL).** This is the quality level of a good lot. It is the per cent defective that can be considered satisfactory as a process average, and represents a level of quality which the producer wants accepted with a high probability of acceptance. In other words, if  $\alpha$  is the producer's risk [see (1.15)], then the level of quality which results in  $100(1 - \alpha)$  % acceptance of the good lots submitted for inspection is called the acceptable quality level.

A lot with relatively small fraction defective (i.e., sufficiently good quality) say,  $p_1$  then we do not wish to reject more often than a small proportion of time is sometimes referred to as a good lot. Usually,

$$\Rightarrow \begin{aligned} P(\text{Rejecting a lot of quality } p_1) &= 0.05 \\ P_a = P(\text{Accepting of a lot of quality } p_1) &= 0.95 \end{aligned}$$

' $p_1$ ' is known as the 'Acceptance Quality Level' and a lot of this quality is considered satisfactory by the consumer.



**Lot Tolerance Proportion or Percentage Defective (LTPD).** The *lot tolerance proportion defective*, usually denoted by  $p_t$ , is the lot quality which is considered to be bad by the consumer. The consumer is not willing to accept lots having proportion defective  $p_t$  or greater.  $100 p_t$  is called *Lot Tolerance Percentage Defective*. In other words, this is the quality level which the consumer regards as rejectable and is usually abbreviated as *R.Q.L.* (*Rejecting Quality Level*). A lot of quality  $p_t$  stands to be accepted some arbitrary and small fraction of time, usually 10%.

**Process Average Fraction Defective ( $\bar{p}$ ).**  $\bar{p}$  represents the quality turned out by the manufacturing process over a long period of time. In industry, the quality of any process tends to settle down to some level which may be expected to be more or less the same everyday for a particular machine. If this level could be maintained and if the process is working free from assignable causes of variation, the inspection could often be dispensed with. But in practice, as a result of failure of machine and men, the quality for the product may suddenly deteriorate. The process average of any manufactured product is obtained by finding the percentage of defectives in the product over a fairly long time.

**Consumer's Risk.** Any sampling scheme would involve certain risk on the part of the consumer—in the sense that he has to accept certain percentage of undesirably bad lots, *i.e.*, lots of quality  $p_t$  or greater fraction defective. More precisely, the probability of accepting a lot with fraction defective  $p_t$  is termed as consumer's risk and is written, as  $P_c$ . Usually it is denoted by  $\beta$ . This is taken by Dodge and Romig as 10% or 0.10.

$$\text{Consumer's risk} = P_c = P [\text{accepting a lot of quality } p_t] = \beta \quad \dots(1.14)$$

**Producer's Risk.** The producer has also to face the situation that some good lots will be rejected. He might demand adequate protection against such contingencies happening too frequently just as the consumer can claim reasonable protection against accepting too many bad lots. The probability of rejecting a lot with  $100 \bar{p}$  as the process average percentage defective is called the producer's risk  $P_p$  and is usually denoted by  $\alpha$ . Thus

$$\text{Producer's risk} = P_p = P (\text{of rejecting a lot of quality } \bar{p}) = \alpha \quad \dots(1.15)$$

**Rectifying Inspection Plans.** In the following sections we shall discuss lot by lot sampling plans in which a specified quality objective is attained through corrective inspection of rejected lots. The inspection of the rejected lots and replacing the defective pieces found in the rejected lots by the good ones, eliminates the number of defectives in the lot to a great extent, thus improving the lot quality. These plans are called '*Rectifying Inspection Plans*' and were first introduced by Harold F. Dodge and Harry G. Romig of the Bell Telephone Laboratories before World War II. These plans enable the manufacturer to have an idea about the average quality of the product that is likely to *result* at a given stage of manufacture through the combination of production, sampling inspection and rectification of rejected lots.

Most of the rectifying inspection plans for lot by lot sampling call for 100% inspection of the rejected lots and replacing the defective pieces found by good ones. The two important points related to rectifying inspection plans are :

- (i) The average quality of the product after sampling and 100% inspection of rejected lots, called Average Outgoing Quality (AOQ); and
- (ii) The average amount of inspection required for the rectifying inspection plan, called Average Total Inspection (ATI).



**Average Outgoing Quality Limit (AOQL).** Sometimes the consumer is guaranteed a certain quality level after inspection—regardless of what quality level is being maintained by the producer. Let the producer's fraction defective, *i.e.*, lot quality before inspection be '*p*'. This is termed as '*incoming quality*'. The fraction defective of the lot after inspection is known as '*outgoing quality*' of the lot. The expected fraction defective remaining in the lot after the application of the sampling inspection plans is termed as Average Outgoing Quality (AOQ)  $\bar{p}$ . Obviously, it is a function of the incoming quality '*p*'.

**Remark.** For rectifying inspection single sampling plan (see § 1-12) calling for 100% inspection of the rejected lots, the AOQ values are given by the formula :

$$\bar{p} = AOQ = \frac{p(N-n)P_a}{N} \quad \dots(1-16)$$

where *N* is lot size, *n* is sample size and  $P_a$  is the probability of acceptance of the lot. Formula (1-16) assumes that all defectives found are repaired or replaced by good pieces. Since we look for defective pieces in the uninspected portion of accepted lots (involving *N* - *n* items) and since *p* is the probability of finding a defective, there will on the average be *p*(*N* - *n*) defective items. Since  $P_a$  is the probability of acceptance of the lot, the sampling plan will on the average turn out lots that contain *p* ·  $P_a$  (*N* - *n*) defective items. Consequently, on dividing by *N*, we get AOQ as a fraction defective given by (1-16).

If *n* is small compared with *N*, then a good approximation of the outgoing quality is given by :

$$\bar{p} = AOQ = p P_a \quad \dots(1-16a)$$

If the defective pieces found are not repaired or replaced, then the formula must be modified to

$$AOQ = \frac{p(N-n)P_a}{N-np-p(1-P_a)(N-n)} = \frac{p(N-n)P_a}{N-p[nP_a+N(1-P_a)]} \quad \dots(1-16b)$$

This formula is not generally used and if *p* is small, there is not much difference between (1-16a) and (1-16b).

In general, if *p* is the incoming quality and a rectifying inspection plan calling for 100% inspection of the rejected lots is used, then the AOQ of the lot will be given by :

$$AOQ = p P_a(p) + 0 \cdot [1 - P_a(p)] = p P_a(p) \quad \dots(1-16c)$$

because (i)  $P_a(p)$  is the probability of accepting the lot of quality '*p*' and when the lot is accepted on the basis of the inspection plan, the outgoing quality of the lot will be approximately same as the incoming lot quality '*p*'; and

(ii)  $1 - P_a(p)$  is the probability of rejection of the lot and when the lot is rejected after sampling inspection and is subjected to 100% screening and rectification, the AOQ is zero.




Fig. 1-17

For a given sampling plan, the value of AOQ can be plotted for different values of *p* to obtain the AOQ curve as given in Fig. 1-17:

From (1-16c), we find that if *p* = 0, *i.e.*, the lot is 100% O.K. then AOQ = 0 and if *p* = 1 *i.e.*, lot is 100% defective then  $P_a(p) = 0$  and so AOQ = 0. For other values of *p* lying between 0



and 1, the AOQL will be positive and will have a maximum value for some value of the incoming quality  $p$ . The maximum value of  $\tilde{p}$  subject to variation in  $p$  is called the Average Outgoing Quality Limit ( $\tilde{p}_L$ ). If  $p_M$  is the value of  $p$  which maximises  $\tilde{p}$  in (1.16), then

$$\tilde{p}_L = \text{A.O.Q.L.} = \frac{p_M \cdot P_a(N-n)}{N} \quad \dots(1.16d)$$

where it should be remembered that  $P_a$  is to be computed for  $p = p_M$ . Re-writing (1.16d), we have

$$\text{AOQL} = \frac{y}{n} \left( 1 - \frac{n}{N} \right) \quad \dots(1.16e)$$

where  $y = np_M \cdot P_a$ , has been tabulated by Dodge and Romig for various values of  $n$  (sample size) and  $c$  (acceptance number of sampling plan, *i.e.*, maximum allowable number of defectives in the sample). The AOQL measures the long-term protection given by the plan to the user in the worst situation.

It may be pointed out that AOQL curve ( $\tilde{p}_L$  plotted against  $p$ ) will reach a maximum value and then recede, since the poorer the quality of the incoming product (*i.e.*, larger the value of  $p$ ) the fewer lots will be accepted and more will be inspected 100% and made acceptable.

**OC Curve.** Operating characteristic (OC) curve of a sampling plan is a graphic representation of the relationship between the probability of acceptance  $P_a(p)$  or generally denoted by  $L(p)$ , for variations in the incoming lot quality ' $p$ ' (fraction defective in the lot). For five general points on the OC curve, see § 1.12.4.

**Average Sample Number (ASN) and Average Amount of Total Inspection.** The average sample number (ASN) is the expected value of the sample size required for coming to a decision about the acceptance or rejection of the lot in an acceptance-rejection sampling plan. Obviously it is a function of the incoming lot quality  $p$ . On the other hand, the expected number of items inspected per lot to arrive at a decision in an acceptance-rectification sampling inspection plan calling for 100% inspection of the rejected lots is called average amount of total inspection (ATI). Obviously ATI is also a function of the lot quality  $p$ .

We observe that

$$\text{ATI} = \text{ASN} + (\text{Average size of inspection of the remainder in the rejected lots}) \quad \dots(1.17)$$

Thus, if the lot is accepted on the basis of the sampling inspection plan then  $\text{ATI} = \text{ASN}$ , otherwise  $\text{ATI} > \text{ASN}$ . In other words ASN gives the average number of units inspected per accepted lot.

For example, if a single sampling acceptance - rejection plan is used, the number of items inspected from each lot will be the corresponding sample size  $n$ , *i.e.*,

$$\text{ASN} = n, \quad \dots(1.17a)$$

and this will be true, independently of the quality of the submitted lots.

However, for an acceptance-rectification single sampling plan calling for 100% inspection of the rejected lots, additional  $(N - n)$  items will have to be inspected for each rejected lot,



where  $N$  is the lot size. Thus, in this case, the number of items inspected per lot varies from lot to lot and is equal to  $n$  if the lot is accepted and equal to  $N$  if the lot is rejected on the basis of the sampling inspection plan. Hence the average amount of total inspection is a function of the lot quality ' $p$ ' and is given by :

$$ATI = nL(p) + N[1 - L(p)] \quad \dots(1.17b)$$

where  $L(p) = P_a(p)$  is the probability of acceptance of the lot of quality  $p$  on the basis of the sampling inspection. Rewriting (1.17b), we get

$$\begin{aligned} ATI &= nL(p) + (N - n + n) [1 - L(p)] \\ &= nL(p) + (N - n) [1 - L(p)] + n[1 - L(p)] \\ &= n + (N - n) [1 - L(p)] \end{aligned} \quad \dots(1.17c)$$

**Remarks 1.** In single sampling inspection plan, the common practice is to inspect the entire sample even though the decision to accept or reject the lot is reached before the entire sample is inspected. Hence ASN in a single sampling plan is  $n$ . Similarly in a double sampling plan, the entire first sample is always inspected.

2. The actual sample size cannot be fractional but the expected sample size may be obtained to the nearest decimal required.

3. The ASN and ATI plotted against the lot quality ' $p$ ' give the ASN curve and ATI curve respectively. These are useful in comparing the efficiency and costs of the sampling inspection plans. In some situations like destructive testing or variables inspection, the rectification of the rejected lot is not feasible or practicable and the ATI curves are not used. In such situations ASN curve is used.

## 1-12. SAMPLING INSPECTION PLANS FOR ATTRIBUTES

The commonly used sampling inspection plans for attributes and count of defects are :

(i) Single sampling plan, (ii) Double sampling plan, and, (iii) Sequential sampling plan.

The requirements (a) and (b) in § 1-11 on page 1-45 will be satisfied provided  $p_t$ ,  $p$  and  $P_c$  are low. Using these principles, H.E. Dodge and H.G. Romig have developed a number of sampling plans which we shall discuss below. These plans enable us to judge the average quality of the product at a given stage of manufacturing process through the combination of production, sampling inspection and rectification of rejected lots. Dodge and Romig average quality protection plans are essentially based upon the AOQL.

**1-12-1. Single Sampling Plan.** If the decision about accepting or rejecting a lot is taken on the basis of one sample only, the acceptance plan is described as single sampling plan. It is completely specified by three numbers  $N$ ,  $n$  and  $c$ , where :

$N$  is the lot size,

$n$  is the sample size, and

$c$  is the acceptance number, i.e., maximum allowable number of defectives in the sample.

The single sampling plan may be described as follows :

1. Select a random sample of size  $n$  from a lot of size  $N$ .
2. Inspect all the articles included in the sample. Let  $d$  be the number of defectives in the sample.
3. If  $d \leq c$ , accept the lot, replacing defective pieces found in the sample by non-defective (standard) ones.